










- GB Assembly instructions
 DE Montageanleitung
 FR Notice de montage
 NL Handleiding voor de montage
 IT Istruzioni di montaggio
 HU Szerelési útmutató
 ES Instrucciones de montaje
- PL Instrukcja montażu
 CZ Montážní návod
 SK Návod na montáž
 HR Montaže
 TR Montaj talimat
 RO Instrucțiuni de montaj
 RU Инструкция по монтажу



®

Service • Assistenza • Dienstverlening • Serwis
Servis • Szerviz • Servizio • Usluga • Сервисная Служба

shop • gescäft • boutique • sklep • winkel • магазин
 negozio • bolt • tienda • obchod • dućan • maġaza • magazin

DESJO

Nr. • No. • N° • Номер • Č. • Sz. • Ne
 13 -- 05

Typ • Type • Tip • Тип • Tipo • Тип
 41


000 X 000 X 000

ABC D 03 06 PP 03/03 1/9

000 X 00 X 00 cm

000 X 00 X 00 kg

1/2



| | | | | | | | | | |
|--|-------|-----|----|-----|-----|-----|-----|-----|-----|
| | φ8x30 | D01 | x8 | D09 | x8 | T02 | x34 | T01 | x34 |
| | φ6x28 | L50 | x8 | T02 | x34 | T01 | x34 | | |

| | | | | | |
|--|-------|-----|-----|-----|-----|
| | φ6x28 | W03 | x12 | K01 | x1 |
| | | S01 | x8 | C05 | x14 |

| | | | | | | | |
|--|-------|-----|----|-----|----|-----|----|
| | L-350 | P08 | x2 | W14 | x8 | W34 | x8 |
|--|-------|-----|----|-----|----|-----|----|

| | | | | | | | |
|--|--------|-----|----|-----|-----|-----|-----|
| | 4x16 | B01 | x6 | W02 | x12 | | |
| | 3.5x20 | W04 | x4 | W09 | x2 | W40 | x14 |

| | | | | | | | |
|--|--------|-----|----|-----|----|-----|-----|
| | 3.5x20 | W04 | x4 | W09 | x2 | W40 | x14 |
|--|--------|-----|----|-----|----|-----|-----|

| | | | | | | | |
|--|--------|-----|----|-----|----|-----|-----|
| | 3.5x20 | W04 | x4 | W09 | x2 | W40 | x14 |
|--|--------|-----|----|-----|----|-----|-----|



1


| | |
|-------|-----|
| P08 | X2 |
| L-350 | |
| φ8x30 | |
| D01 | X38 |
| T02 | X34 |
| T01 | X8 |
| 6x8 | |
| W34 | X4 |

2


| | |
|-------|-----|
| φ6x28 | X8 |
| D09 | X8 |
| φ8x30 | |
| D01 | X16 |

| | |
|--------|-----|
| L 50 | |
| W03 | X8 |
| K01 | X1 |
| W04 | X1 |
| W40 | X14 |
| 3.5x20 | X4 |
| 6.3x24 | X4 |


4 (x2)




5




6



7






8








9


10 (x2)



11




12




W09 3,5x30 x2

13 (x2)



W14 3x13 x8 P08 x2



14



C05 x14

C05 **W40**

15



max 4kg

