



PORTO

→ 135 + 190 \ 31



x 30 a	x 16 b	x 9 c	x 9 d	x 6 e	x 6 f		
x 4 (M4-12) i	x 4 j	x 1 kpl. k	x 2 l	x 1 m	x 5 n		
x 2 r	x 2 s	x 8 (6,2x16) t	x 8 (3,5x30) u	x 24 (3,5x16) w	x 14 (3x13) x	x 100 y	x 1 z
x 9 g	x 4 (182 mm) h	x 1 (250 mm) o	x 1 kpl. p	 q	 r	 60 min 	

1 - FAZY MONTAŻU

A - OZNACZENIE ELEMENTÓW

a - OZNACZENIE AKCESORIÓW



